

Final Reclamation Inspection

December 15th, 2023

Operator: Simcoe LLC - 10749

Location ID: 333659

Inspection Document #: 714000243

La Plata County, CO

Township: NESE 23 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Picolli A2
Location ID: 333659




Photo 1. View of the well disturbance from the entrance facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08968

12/15/23
+37.175686,-107.788497
36° NE

