

FORM
43Rev
05/21State of Colorado
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

OGCC RECEPTION

Receive Date:

12/27/2023

Document Number:

403637059

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 47120 Contact Person: Dane Olson
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (307) 760-5319
Address: P O BOX 173779 Fax: ()
City: DENVER State: CO Zip: 80217-3779 Email: Dane_Olson@oxy.com

Identification Information

API Number: 05 - 123-18818 OGCC Facility ID: 251015 Initial Form 19 or 27 Document number:
Facility Name: HSR-DAVIS, V Facility Number: 5-26A Facility Type: WELL
Location QtrQtr: SWNW Section: 26 Township: 3N Range: 67W Meridian: 6
County: WELD Field Name: WATTENBERG
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional
Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ NettedSample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 251015 Facility Name: HSR-DAVIS, V 5-26A Facility Type: Oil and Gas Well
Location: QtrQtr: SWNW Sec: 26 Twp: 3N Range: 67W Meridian: 6
County Name: WELD Latitude: 40.198028 Longitude: -104.865697

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 115517 Document Name: Size of file in bytes: 34816 File Name: 2023_10_03_SP_05_123_18818_C_Isotech_NG4_ECMC.xls
SampleType: Matrix:
Facility ID: 251015 Sample ID: 654759 Sample Name: SP_05_123_18818_C Sample Date: 10/03/2023
Collection Point: PRDC Matrix: GAS Pre Post: Production Gas Sample
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: ISOTECH Lab Sample ID: 893563

Batch ID: 115513		Document Name: Size of file in bytes: 36864		File Name: 2023_10_03_BW_05_123_18818_BHD_Isotech_NG_4_ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 251015	Sample ID: 654754	Sample Name: BW_05_123_18818_BHD		Sample Date: 10/03/2023	
Collection Point: BDH	Matrix: GAS	Pre Post: Bradenhead Water Sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 892441		

Batch ID: 115514		Document Name: Size of file in bytes: 25600		File Name: 2023_10_03_BW_05_123_18818_BHD_SGS_DRO_ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 251015	Sample ID: 654756	Sample Name: BW_05_123_18818_BHD		Sample Date: 10/03/2023	
Collection Point: BDH	Matrix: WATER	Pre Post: Bradenhead Water Sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59060-1		

Batch ID: 115515		Document Name: Size of file in bytes: 69632		File Name: 2023_10_03_BW_05_123_18818_BHD_SGS_ECM C.xls	
SampleType: _____			Matrix: _____		
Facility ID: 251015	Sample ID: 654757	Sample Name: BW_05_123_18818_BHD		Sample Date: 10/03/2023	
Collection Point: BDH	Matrix: WATER	Pre Post: Bradenhead Water Sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59060-1		

Batch ID: 115513		Document Name: Size of file in bytes: 36864		File Name: 2023_10_03_BW_05_123_18818_BHD_Isotech_NG_4_ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 251015	Sample ID: 654755	Sample Name: BW_05_123_18818_BHD		Sample Date: 10/03/2023	
Collection Point: BDH	Matrix: GAS	Pre Post: Bradenhead Water Sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 892441		

Batch ID: 115516		Document Name: Size of file in bytes: 31232		File Name: 2023_10_03_BW_05_123_18818_BHD_TRIP_BLA NK_SGS_ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 251015	Sample ID: 654758	Sample Name: BW_05_123_18818_BHD_TRIP_BLANK		Sample Date: 10/03/2023	
Collection Point: TB	Matrix: WATER	Pre Post: Trip Blank			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59059-1		

Sample Facility Attachment:

No Facility Attachment

Sample COGCC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
654758	123-18818	HSR-DAVIS, V 5-26A	Trip Blank

General Comments

User Group	Comment	Comment Date
Engineer	The data submitted by the operator can be accessed through the COGIS data system.	12/28/2023
Total: 1 comment(s)		