

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403267454

Date Received:

12/21/2022

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Labowskie, Steve

steve.labowskie@state.co.us

\_General

sjninspections@ikavenergy.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 702500722

Inspection Date: 11/03/2022

FIR Submit Date: 11/03/2022

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

### LOCATION - Location ID: 334302

Location Name: HESTER GAS UNIT-M34N9W Number: 2NENE County: LA PLATA

Qtrqtr: NENE Sec: 2 Twp: 34N Range: 9W Meridian: M

Latitude: 37.212640 Longitude: -107.790142

### FACILITY - API Number: 05-067- -00 Facility ID: 295866

Facility Name: HESTER Number: 4

Qtrqtr: NENE Sec: 2 Twp: 34N Range: 9W Meridian: M

Latitude: 37.212640 Longitude: -107.790142

### CORRECTIVE ACTIONS:

1 ☒ CA# 165906

Corrective Action: Confirm annual calibration has been completed or perform annual calibration per rule 430.d.(1).

Date: 12/03/2022

Response: CA COMPLETED

Date of Completion: 11/30/2022

Operator Comment: Calibration completed 11/30/2022.

COGCC Decision:

Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 165907

Corrective Action: All unused equipment must be returned to use or stored off location per rule 606.

Date: 11/11/2022

Response: CA COMPLETED

Date of Completion: 11/09/2022

Operator  
Comment: Removed unused piping and crossover stairs.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 165908

Corrective Action: Install sign to comply with Rule 605.h.

Date: 01/03/2023

Response: CA COMPLETED

Date of Completion: 11/09/2022

Operator  
Comment: Added tank volume to pit sign.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA Completed. See attached completion photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Gabby Riley

Signed: \_\_\_\_\_

Title: Permitting Specialist I

Date: 12/21/2022 9:59:22 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403267454	FIR RESOLUTION SUBMITTED
403267519	Hester 2 & 4; CA Completion Photos

Total Attach: 2 Files