



99999999

## WELL SITE INSPECTION FORM



WELL NAME D.J. Tuttle API NUMBER 05 - (121 - 6905)  
OPERATOR Kingwood Oil PERMIT NUMBER \_\_\_\_\_  
LOCATION SUNE 28-2N-54W COUNTY Washington  
FIELD Xenia W. INSPECTOR Bin Day

## AL/PA/DA INSPECTION RESULTS:

## WELL STATUS:

PASS(Y) ☒ FAIL(N) \_\_\_\_\_ DATE 6-29-89 FN \_\_\_\_\_ FD \_\_\_\_\_ WO \_\_\_\_\_

=====

DATE OF INSPECTION BEFORE/DURING DRILLING \_\_\_\_\_

CASING SIZE \_\_\_\_\_ DEPTH SET \_\_\_\_\_ CMT VOL \_\_\_\_\_ WOC \_\_\_\_\_  
CONSISTENT WITH APD CASING PROGRAM? \_\_\_\_\_ RETURNS \_\_\_\_\_  
RIG \_\_\_\_\_ BOP'S \_\_\_\_\_ CONTACT \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION \_\_\_\_\_

PIPE SET? \_\_\_\_\_ COMPLETION RIG/ACTIVITY \_\_\_\_\_  
DRILLING PITS: CLOSED \_\_\_\_\_ OPEN \_\_\_\_\_ WELLHEAD SYSTEM INSTALLED \_\_\_\_\_  
TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ WELL SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_  
SKIM PIT: \_\_\_\_\_ gal TANKS: ( ) \_\_\_\_\_ bbls  
EQUIPMENT \_\_\_\_\_

BRADENHEAD PRESSURE \_\_\_\_\_ FLUID: NO \_\_\_\_\_ YES \_\_\_\_\_ TYPE \_\_\_\_\_  
METER RUN: YES \_\_\_\_\_ NO \_\_\_\_\_ WELL STATUS: PR \_\_\_\_\_ TA \_\_\_\_\_ SI \_\_\_\_\_ WELL CAT 3- \_\_\_\_\_

## AL/PA/DA INSPECTION

DATE PLUGGED: 12-1-65 DATE PERMIT EXPIRED: \_\_\_\_\_  
HOLE PLUGGED: YES ☒ NO \_\_\_\_\_ PITS BACKFILLED: YES ☒ NO \_\_\_\_\_  
MATERIAL BURIED: YES ☒ NO \_\_\_\_\_ NA \_\_\_\_\_ SITE CLEAN: YES ☒ NO \_\_\_\_\_  
BOND RELEASE OK: YES ☒ NO \_\_\_\_\_ FED \_\_\_\_\_ HOLE MARKER: YES \_\_\_\_\_ NO ☒

DATE OF SAFETY/STATUS INSPECTION \_\_\_\_\_

COMMENTS native



00054563