

Final Reclamation Inspection

December 5th, 2023

Operator: Hilcorp Energy Company - 10133

Location ID: 326426

Inspection Document #: 714000234

La Plata County, CO

Township: SENW 29 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Wilson 34-9 29-1
Location ID: 326426



Photo 1. View of the offsite tanks/separator location facing north.



Inspection Photos
Location Name: Wilson 34-9 29-1
Location ID: 326426



Photo 2. View of the well and domestic tap disturbance taken from the southern edge facing north. Note: Interim vegetation was not fully assessed due to snowy conditions. Tubing debris observed on location.



Inspection Photos
Location Name: Wilson 34-9 29-1
Location ID: 326426

12/5/23
+37.164552,-107.852679
197° S



Photo 3. View of large musk thistle patch observed along the well location access road.