

Final Reclamation Inspection

December 15th, 2023

Operator: Simcoe LLC - 10749

Location ID: 312036

Inspection Document #: 714000238

La Plata County, CO

Township: NWNW 30 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bellino 1-3
Location ID: 312036

12/15/23
+37.169041,-107.765198
124° SE



Photo 1. View of the well location signs.



Inspection Photos
Location Name: Bellino 1-3
Location ID: 312036



Photo 2. View of unused and surface owner equipment stored in the northern interim reclamation area.

Inspection Photos
Location Name: Bellino 1-3
Location ID: 312036

12/15/23
+37.168789,-107.765280
339° N



Photo 3. Additional surface owner equipment stored on the northern edge of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515

Inspection Photos
Location Name: Bellino 1-3
Location ID: 312036



Photo 3. View of musk thistle observed in the northern and eastern interim reclamation areas.