

Final Reclamation Inspection

December 15th, 2023

Operator: Simcoe LLC - 10749

Location ID: 325591

Inspection Document #: 714000239

La Plata County, CO

Township: NENW 19 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lunt 19-01
Location ID: 325591

12/15/23
+37.181244,-107.763876
145° SE




Photo 1. View of the well disturbance from the entrance facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06659

Inspection Photos
Location Name: Lunt 19-01
Location ID: 325591



12/15/23
+37.181138,-107.763912
201° S

Photo 2. View of southern interim reclamation area facing south. Note: interim vegetation was not fully assessed due to snowy conditions.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515