

Inspection Photos
Location Name: TREBOR B/11-20
Location ID: 414332



Photo #1

Trebor B 11-20 (123-30731) Wellsite
Temporarily Abandoned | TA
CA: Overgrown Vegetation
prior photo



Photo #2

Trebor B 11-20 Wellsite
Temporarily Abandoned | TA
Overgrown Vegetation, NOW mitigated
Date: 12-08-2023 (Operator photo)



Inspection Photos

Location Name: TREBOR B/11-20

Location ID: 414332



Photo #3

Trebor B11-6, 11-3, 11-18, 11-20, 11-21 Battery site

Inactive | Shut-down

Formerly served:

Trebor B11-4, B 11-19 ;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 326889

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources