

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad
Location #: 335594



**Location Overview: Location is within High
Priority/Density/NSO/Black Bear Habitat areas. Location is
approximately 186 yards from East Fork Parachute Creek.
Section/Township/Range: 29 5S95W**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad
Location #: 335594



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad
Location #: 335594



Photo # 1210 Stockpiled soils with no BMP's/soils appear to be impacted



Photo # 1211 Stockpiled soils with no BMP's/soils appear to be impacted

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad
Location #: 335594



Photo # 1212 Stockpiled soils with no BMP's/soils appear to be impacted



Photo # 1213 Stockpiled soils with no BMP's/soils appear to be impacted

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad
Location #: 335594



**Photo # 1214 Chemical tank containment full of fluid/failure
to maintain chemical BMP**