

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 1200 From entrance to location



Photo # 1201 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 1202 Sign at entrance to location



Photo # 1203 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 1204 Location



Photo # 1205 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 1206 Location



Photo # 1207 All wellhead signs lack required information

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 1208 All wellhead signs lack required information



Photo # 1209 All wellhead signs lack required information