

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE J15 595 Pad

Location #: 335568



Photo # 840 From entrance to location



Photo # 841 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE J15 595 Pad

Location #: 335568



Photo # 842 Location



Photo # 843 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE J15 595 Pad

Location #: 335568



Photo # 844 Location



Photo # 845 Entrance to location lacks signage

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE J15 595 Pad

Location #: 335568



Photo # 846 Methanol tank missing required info



Photo # 847 Methanol tank missing required info

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE J15 595 Pad

Location #: 335568



Photo # 848 Methanol tank



Photo # 849 Methanol tank label contains inaccurate /incorrect info

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE J15 595 Pad

Location #: 335568




Photo # 850 Wellhead lacks signage




Photo # 851 Wellhead sign not conspicuously located, appears to be buried in snow.

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE J15 595 Pad

Location #: 335568



Photo # 852 Tank battery lacks signage




Photo # 853 Secondary containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE J15 595 Pad

Location #: 335568



Dec 26, 2023 at 1:08:12 PM

Photo # 854 Secondary containment liner needs maintenance



Dec 26, 2023 at 1:08:23 PM

Photo # 855 Secondary containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE J15 595 Pad

Location #: 335568



Photo # 856 Secondary containment liner needs maintenance



Photo # 857 Secondary containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE J15 595 Pad

Location #: 335568




Photo # 858 Secondary containment liner needs maintenance



Photo # 859 Secondary containment liner needs maintenance