

Reclamation Corrective Action Inspection

00000000

R 34 AT ENTRANCE GO E / APX 2.5 MI TO
N 1/4 MI THEN CONT SE / 705' TO WELL SITE
PS PT (40.245283, -104.516305)
annual and perennial vegetation in

reclamation phase, perennial vegetation
in
or observed

ent of perennial grasses and forbs,
central plan and mowing for annual weeds
C Inspection 712900114, location was
ded with Sandy Loam Native Mix applied

mowing and interseeding have been done



From center of battery pad facing W



From edge of battery pad facing
well pad



From center of battery pad facing NNE



From center of battery pad facing E



From center of battery pad facing S



From center of battery pad facing SSW
Tracks from cattle traffic



From well pad facing NNE
toward access road