

Final Reclamation Inspection

November 1st, 2023

Operator: Elm Ridge Exploration Company LLC -
26625

Location ID: 333362

Inspection Document #: 714000108

La Plata County, CO

Township: CSE 7 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FW Terrell GU 1
Location ID: 333362



Photo 1. View of the project area taken from the southern edge facing center.

Inspection Photos
Location Name: FW Terrell GU 1
Location ID: 333362



Photo 2. Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: FW Terrell GU 1
Location ID: 333362



Photo 3. Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Note: Location appears consistent with adjacent reference area, see photo 4.

Inspection Photos
Location Name: FW Terrell GU 1
Location ID: 333362



Photo 4. Reference area comprised of sage brush, crested wheatgrass and rabbit brush.