

Inspection Photos

12/27/2023

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335000

Inspection Doc: 696205494

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335000



December 27, 2023



December 27, 2023

Photo 1: Photos taken from the west end of the Location. Photos provide an overview of the Location from northeast to southeast.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335000



Photo 2: Tank battery facility on the south end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #104

Location ID: 335000



Photo 3: Photo shows the excavation associated with the PAd well 045-09327 has not been backfilled. Photo top right shows gap in fencing around wells; BMPs to prevent livestock access to the wells and excavation is inadequate.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources