

## Inspection Photos

Location Name: TREBOR B-65N64W/11NESW

Location ID: 310599



**Photo #1**

**Trebor B 11-25 (123-26657) Wellsite**

**Temporarily Abandoned | TA**

**CA: Overgrown Vegetation**

*prior photo*



**Photo #2**

**Trebor B 11-25 Wellsite**

**Temporarily Abandoned | TA**

**Overgrown Vegetation, NOW mitigated**

**Date: 12-08-2023 (Operator photo)**



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: TREBOR B-65N64W/11NESW

Location ID: 310599



### Photo #3

Trebor B 11-25 Battery site

**Inactive | Shut-down**

*Formerly served:*

*Trebor B11-13, B11-14 ;*

*Plugged & Abandoned | PA*

**Equipment Documented; Loc ID: 310599**

*prior photo*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources