

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE D21 595 Pad

Location #: 335673



Dec 26, 2023 at 11:59:13 AM



Dec 26, 2023 at 11:59:50 AM
CO

Photo # 784 From entrance to location

Photo # 785 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE D21 595 Pad

Location #: 335673



Photo # 786 Location



Photo # 787 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE D21 595 Pad

Location #: 335673



Photo # 788 Methanol tank labeling contains inaccurate /incorrect information



Photo # 789 Methanol tank



Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE D21 595 Pad

Location #: 335673



Photo # 790 Methanol tank labeling contains inaccurate /incorrect information




Photo # 791 Wellhead sign contains inaccurate/incorrect info

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE D21 595 Pad

Location #: 335673



Photo # 792 Wellhead sign contains inaccurate/incorrect info

Photo # 793 Unlabeled container/contents unknown

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE D21 595 Pad

Location #: 335673



Photo # 794 Production tank lacks secondary containment



Photo # 795 Tank battery lacks signage



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources