

Inspection Photos

API: 071-07252

Operator: OGRIS OPERATING LLC

Inspection Date: 12/28/2023

County: Las Animas



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-07252 | Date: 12/28/2023

Inspection Photos



Photo 2. Facing north at the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-07252 | Date: 12/28/2023

Inspection Photos



Photo 3. Facing toward the fill slope which is stabilized with vegetation.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-07252 | Date: 12/28/2023