

Interim Reclamation and Stormwater Inspection

Date: 12/28/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 425346

Inspection Document #: 708200782

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: McClellan PC LG03-78HN

Location ID: 425346




Photo 1. Stained soil and a container with unknown fluid observed near wellhead.

Inspection Photos
Location Name: McClellan PC LG03-78HN
Location ID: 425346



Photo 2. Labels and emergency contact info are not legible and require replacement.



Photo 3. Labels and emergency contact information are not legible and require replacement.

Inspection Photos
Location Name: McClellan PC LG03-78HN
Location ID: 425346



Photo 4. Loadout line collection pot does not appear to be in use; any unused equipment shall be returned to service or removed.

Inspection Photos
Location Name: McClellan PC LG03-78HN
Location ID: 425346



Photo 5. North of wellhead. Interim areas do not appear to be progressing towards Rule 1003 regulations and standards with evidence of bare/exposed soils and undesirable vegetation (e.g. russian thistle and kochia) observed. Additional reclamation activities are required.

Inspection Photos
Location Name: McClellan PC LG03-78HN
Location ID: 425346



Photo 6. East of wellhead; see comments in Photo 5.

Inspection Photos
Location Name: McClellan PC LG03-78HN
Location ID: 425346



Photo 7. South of wellhead; see comments in Photo 5.

Inspection Photos
Location Name: McClellan PC LG03-78HN
Location ID: 425346



Photo 8. Northwest of production equipment; see comments in Photo 5.

Inspection Photos
Location Name: McClellan PC LG03-78HN
Location ID: 425346



Photo 9. North of production equipment, facing southwest; see comments in Photo 5.

Inspection Photos
Location Name: McClellan PC LG03-78HN
Location ID: 425346



Photo 10. North of production equipment, facing east; see comments in Photo 5.

Inspection Photos
Location Name: McClellan PC LG03-78HN
Location ID: 425346



Photo 11. North of production equipment, facing east; see comments in Photo 5.

Inspection Photos
Location Name: McClellan PC LG03-78HN
Location ID: 425346



Photo 12. Google Earth aerial imagery taken circa 11/2023. Photo illustrates interim areas that must be reclaimed (red outline). Areas previously used for drilling/completions can be seen inside of the red outline.