

Interim Reclamation and Stormwater Inspection

Date: 12/28/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 435720

Inspection Document #: 708200783

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bulleit Federal PC LG 04-62HN
Location ID: 435720



Photo 1. Stained soil observed around compressor station.

Inspection Photos

Location Name: Bulleit Federal PC LG 04-62HN

Location ID: 435720



Photo 2. Stained soil observed around compressor station.

Inspection Photos
Location Name: Bulleit Federal PC LG 04-62HN
Location ID: 435720



Photo 3. Stained soil observed around compressor station.

Inspection Photos
Location Name: Bulleit Federal PC LG 04-62HN
Location ID: 435720



Photo 4. NFPA placard at produced water tank is not legible.

Inspection Photos

Location Name: Bulleit Federal PC LG 04-62HN

Location ID: 435720



Photo 5. Western interim areas appear to be progressing towards Rule 1003 regulations and standards with evidence of desirable perennial vegetation observed. The interim areas also appear to have been recently mowed, therefore, a follow-up inspection will be conducted at a later date to verify vegetative compliance during the next growing season.

Inspection Photos

Location Name: Bulleit Federal PC LG 04-62HN

Location ID: 435720



Photo 6. Northern interim areas; see comments in Photo 5.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 708200783

Inspection Photos

Location Name: Bulleit Federal PC LG 04-62HN

Location ID: 435720



Photo 7. Eastern interim areas; see comments in Photo 5.