

# Interim Reclamation and Stormwater Inspection

Date: 12/28/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 432140

Inspection Document #: 708200784

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: McClellan LG09-72HN  
Location ID: 432140



**Photo 1.** Northern interim areas appear to be progressing towards Rule 1003 regulations and standards with evidence of desirable perennial vegetation observed. The interim areas also appear to have been recently mowed, therefore, a follow-up inspection will be conducted at a later date to verify vegetative compliance during the next growing season.



Inspection Photos  
Location Name: McClellan LG09-72HN  
Location ID: 432140



**Photo 2.** Eastern interim areas; see comments in Photo 1.



Inspection Photos  
Location Name: McClellan LG09-72HN  
Location ID: 432140



**Photo 3.** Southern interim areas; see comments in Photo 1.

Inspection Photos  
Location Name: McClellan LG09-72HN  
Location ID: 432140



**Photo 4.** Western interim areas; see comments in Photo 1.