

Final Reclamation Inspection

December 29, 2023

Operator: EDGE ENERGY II LLC - 10671

Location ID: 422460

Inspection Document #: 697505038

Larimer County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RAWHIDE FLATS 10-68-16 #1H
Location ID: 422460



Photo 1. Photo taken from the entrance of location off CR7, facing West. Photo illustrates unmanaged weeds. Also gravel and the cattle guard remain- refer to Photo 2.



Photo 2. Photo taken from the entrance of location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: RAWHIDE FLATS 10-68-16 #1H
Location ID: 422460



Photo 3. Photo taken from the eastern access road, facing West. Photo illustrates the Operator failed to properly recontour the access road and does not appear to have removed all the gravel. Also, there was no desirable vegetation establishment.



Photo 4. Photo taken from the southeastern location, facing East. Photo illustrates unmanaged weeds which were observed throughout the entire location.

Inspection Photos
Location Name: RAWHIDE FLATS 10-68-16 #1H
Location ID: 422460



Photo 5. Photo taken from an area at the location. Photo illustrates the evidence of drill rows indicating final reclamation was performed. However, there was not any desirable vegetation observed.
Note- there was some straw mulch observed in areas.



Photo 6. Photo taken from an area at the location. Photo illustrates the Operator did a poor job at removing gravel.

Inspection Photos
Location Name: RAWHIDE FLATS 10-68-16 #1H
Location ID: 422460



Photo 7. Photo taken from western location, facing North. Photo illustrates power lines remain at the location, which were installed for oil and gas operations.



Photo 8. Photo taken from western location. Photo illustrates debris left behind.

Inspection Photos
Location Name: RAWHIDE FLATS 10-68-16 #1H
Location ID: 422460



12.29.2023 15:22

Photo 9. Reference are photo taken along the access road, facing East. Reference area to the left of the red-dashed line; unreclaimed access road to the right of the red-dashed line.

