

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FORSTER W-46-11 Pad

Location ID: 323781



Photo # 1544 From entrance to location




Photo # 1545 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FORSTER W-46-11 Pad

Location ID: 323781



Photo # 1546 Location



Photo # 1547 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FORSTER W-46-11 Pad

Location ID: 323781



Photo # 4059 From inspection 708902036 conducted on 10/24/2023 Unmarked deadman



Photo # 6444 From inspection 708902222 conducted on 11/13/2023 Unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FORSTER W-46-11 Pad

Location ID: 323781



Photo # 1548 Unmarked deadman



Photo # 1549 Same unmarked deadman from a different angle

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FORSTER W-46-11 Pad

Location ID: 323781



Photo # 1550 Debris