

**Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC**

**Location Name: Antelope F-15 Pad**

**Loc ID: 429977**

**Inspection: 696305514**



Exhibit A



Exhibit B

**CA:** EAST TANK BATTERY LABELS - #1336 - NFPA and Content. #220404 - Content, Capacity and NFPA. #220403 - NFPA. #220402 - Capacity and Content. #220401 - NFPA. East side of East Tanks - far North Tank - Capacity. Far South Tank - Content, Capacity and NFPA. See photos. Install sign to comply with Rule 605.h.

**CA Resolution:** Operator has installed updated NFPA and Capacity signage on the identified tanks. Contents signage is in the process of being installed to ensure the site complies with Rule 605.h.



**Exhibit A**

**CA:** Tumbleweed Debris build-up at Maintenance Tank. Lid is open to Atmosphere. Comply Rule 606. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.

**CA Resolution:** Operator has appropriately cleared tumbleweed debris to comply with Rule 606, and addressed open lid to prevent any unauthorized discharge to comply with Rule 902.b