

Interim and Stormwater Inspection

December 18, 2023

Operator: Goodwin Energy Management LLC- #98940

Location ID: 320061

Inspection Document #: 709400682

Adams County, CO

SESE Section 8 T3S R62W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Brown-Amoco 44-08
Facility ID: 320061



Photo 1. Photo taken of location sign, facing south.



Photo 2. Photo taken of Tank battery. Photo taken facing southeast.

Inspection Photos
Location Name: Brown-Amoco 44-08
Facility ID: 320061



Photo 3. Photo taken of weed (kochia) on site. Photo taken facing southeast



Photo 4. Photo taken of weed (kochia & russian thistle) along site perimeter . Photo taken facing north.

Inspection Photos
Location Name: Brown-Amoco 44-08
Facility ID: 320061



Dec 18, 2023 at 2:04:18 PM
Piggott Rd
Strasburg CO 80136
United States



Dec 18, 2023 at 2:04:25 PM
Piggott Rd
Strasburg CO 80136
United States

Photo 5. Photo taken of oil at the bottom of crude oil tank in tank battery. Photo taken facing north.

Photo 6. Photo taken of oil at the bottom of crude oil tank in tank battery. Photo taken facing north.



Inspection Photos

Location Name: Brown-Amoco 44-08

Facility ID: 320061

Dec 18, 2023 at 2:05:24 PM
Piggott Rd
Strasburg CO 80136
United States



Photo 7. Photo taken of unmarked pipes on site. Photo taken facing west.

Dec 18, 2023 at 2:05:28 PM
Piggott Rd
Strasburg CO 80136
United States



Photo 8. Photo taken of weeds (Kochia) on site. Photo taken facing west.



Inspection Photos

Location Name: Brown-Amoco 44-08

Facility ID: 320061

Dec 18, 2023 at 2:05:40 PM
Piggott Rd
Strasburg CO 80136
United States



Dec 18, 2023 at 2:05:41 PM
Piggott Rd
Strasburg CO 80136
United States



Photo 9. Photo taken of weed (kochia & russian thistle) along site perimeter . Photo taken facing north.

Photo 10. Photo taken of weed (kochia & russian thistle) along site perimeter . Photo taken facing south.

