

# Final Reclamation Inspection

December 27th, 2023

Operator: Simcoe LLC - 10749

Location ID: 333432

Inspection Document #: 714000258

La Plata County, CO

Township: SWNW 26 34N 9W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Cugnini A1, A3  
Location ID: 333432



12/27/23  
+37.165296,-107.802399  
132° SE

Photo 1. View of the well disturbance from the entrance facing center.



12/27/23  
+37.165573,-107.802575  
144° SE



Inspection Photos  
Location Name: Cugnini A1, A3  
Location ID: 333432



**Photo 2.** View of gully erosion forming in the western interim reclamation area.



Inspection Photos  
Location Name: Cugnini A1, A3  
Location ID: 333432



Photo 3. View of weedy debris observed around active equipment.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #:067-05515



Inspection Photos  
Location Name: Cugnini A1, A3  
Location ID: 333432



**Photo 4.** View of unused equipment observed on location.





Inspection Photos  
Location Name: Cugnini A1, A3  
Location ID: 333432

12/27/23  
+37.165745,-107.801885  
312° NW



**Photo 5.** Reference area comprised of smooth brome.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #:067-05515