

# Final Reclamation Inspection

December 27th, 2023

Operator: Simcoe LLC - 10749

Location ID: 311975

Inspection Document #: 714000259

La Plata County, CO

Township: SENW 23 34N 9W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Linder 23-01 1R, 2, 3, 4  
Location ID: 311975



Photo 1. View of the well disturbance from the entrance facing center.





Inspection Photos

Location Name: Linder 23-01 1R, 2, 3, 4

Location ID: 311975



12/27/23

+37.176765,-107.800577

224° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of musk thistle observed in the northern interim reclamation area.

API #:067-05515



Inspection Photos  
Location Name: Linder 23-01 1R, 2, 3, 4  
Location ID: 311975

12/27/23  
+37.177045,-107.799528  
285° W



**Photo 3.** Large piles of unstabilized soil observed on the northern edge of the disturbance.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #:067-05515



Inspection Photos

Location Name: Linder 23-01 1R, 2, 3, 4

Location ID: 311975



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area comprised of smooth brome, sage brush and juniper.

API #:067-05515