

Final Reclamation Inspection

December 27th, 2023

Operator: Simcoe LLC - 10749

Location ID: 312012

Inspection Document #: 714000260

La Plata County, CO

Township: NESW 26 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cugnini A2, A4
Location ID: 312012



Photo 1. View of the well disturbance from the entrance facing center.

Inspection Photos
Location Name: Cugnini A2, A4
Location ID: 312012

12/27/23
+37.159633,-107.799607
133° SE



Photo 2. View of the eastern interim reclamation area.



Inspection Photos
Location Name: Cugnini A2, A4
Location ID: 312012

12/27/23
+37.159446,-107.799510
90° E



Photo 3. Disturbance is surrounded by an active gravel mine.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #:067-05515