

Final Reclamation Inspection

December 27th, 2023

Operator: Simcoe LLC - 10749

Location ID: 306798

Inspection Document #: 714000261

La Plata County, CO

Township: SESW 19 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lunt 19-01 2
Location ID: 306798



12/27/23
+37.172576,-107.762060
129° SE



Photo 1. View of the well disturbance from the entrance facing center.



12/27/23
+37.172761,-107.762330
266° W



Photo 2. View of the northern interim reclamation area.

Inspection Photos
Location Name: Lunt 19-01 2
Location ID: 306798



12/27/23
+37.171804,-107.761525
286° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Reference area comprised of smooth brome, sagebrush and juniper.

API #:067-05515