

Final Reclamation Inspection

December 27th, 2023

Operator: Simcoe LLC - 10749

Location ID: 334000

Inspection Document #: 714000262

La Plata County, CO

Township: SESW 19 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lunt 19-01 3, 4
Location ID: 334000

12/27/23
+37.172576,-107.762060
129° SE



Photo 1. View of the well disturbance from the entrance facing center.



API #: 067-09512, 09513

Inspection Photos
Location Name: Lunt 19-01 3, 4
Location ID: 334000

12/27/23
+37.172467,-107.761412
310° NW



Photo 2. View of the northern interim reclamation area.



Inspection Photos
Location Name: Lunt 19-01 3, 4
Location ID: 334000



Photo 3. View of debris observed on the eastern edge of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09512, 09513

Inspection Photos
Location Name: Lunt 19-01 3, 4
Location ID: 334000



12/27/23
+37.171804,-107.761525
286° W

Photo 4. Reference area comprised of smooth brome, sagebrush and juniper.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09512, 09513