

Final Reclamation Inspection

December 27th, 2023

Operator: Simcoe LLC - 10749

Location ID: 325762

Inspection Document #: 714000263

La Plata County, CO

Township: SENW 12 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Alice Lorenz 1
Location ID: 325762

12/27/23
+37.208589,-107.780480
174° S



Photo 1. View of the well disturbance from the entrance facing center.



12/27/23
+37.208487,-107.780249
261° W

Inspection Photos
Location Name: Alice Lorenz 1
Location ID: 325762

12/27/23
+37.208300,-107.780270
222° SW



Photo 2. View of the western interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06951

Inspection Photos
Location Name: Alice Lorenz 1
Location ID: 325762

12/27/23
+37.208386,-107.780202
38° NE



Photo 3. Reference area comprised of smooth brome.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06951