

Final Reclamation Inspection

December 27th, 2023

Operator: Simcoe LLC - 10749

Location ID: 334265

Inspection Document #: 714000265

La Plata County, CO

Township: SWNE 13 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fassett 02-13 1
Location ID: 334265



Photo 1. View of the well disturbance from the entrance facing center.



API #: 067-06785

Inspection Photos
Location Name: Fassett 02-13 1
Location ID: 334265



Photo 2. View of musk thistle observed on location and around active equipment.

API #: 067-06785



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Fassett 02-13 1
Location ID: 334265




Photo 3. Large pile of gravel and surface owner equipment stored on location.

Inspection Photos
Location Name: Fassett 02-13 1
Location ID: 334265

12/27/23
+37.193788,-107.773368
177° S



Photo 4. Reference area is a grassy agriculture field.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06785