

# Final Reclamation Inspection

December 27th, 2023

Operator: Simcoe LLC - 10749

Location ID: 326514

Inspection Document #: 714000266

La Plata County, CO

Township: SWSW 10 34N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Huber Lengal Slaughter 2-10  
Location ID: 326514



Photo 1. View of the well disturbance from the entrance facing center.



API #: 067-08231

Inspection Photos

Location Name: Huber Lengal Slaughter 2-10

Location ID: 326514



12/27/23

+37.2252737, -107.738723

49° NE



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of musk thistle observed in the western interim reclamation area.

API #: 067-08231

Inspection Photos

Location Name: Huber Lengal Slaughter 2-10

Location ID: 326514



12/27/23

+37.225075,-107.738781

208° SW



**Photo 3.** Reference area comprised of smooth brome, sagebrush and juniper.