

Inspection Photos
Location Name: Wells Ranch AE 05-12
Location ID: 422345



Photo 1 – Pumping Unit



Photo 2 – Well has been Cut and Capped

Inspection Photos
Location Name: Wells Ranch AE 05-12
Location ID: 422345



Photo 3 – Well Sign



Photo 4 – Pumping Unit

Inspection Photos
Location Name: Wells Ranch AE 05-12
Location ID: 422345



Photo 5 – Wellhead