

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW

Location # 323790

Facility # 456910



Photo # 1907 Domestic tap



Photo # 1908 Domestic tap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW

Location # 323790

Facility # 456910



Photo # 384 From inspection 708902565 conducted on 12/19/2023 PRV vent line lacks cap



Photo # 1909 PRV vent line lacks cap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW

Location # 323790

Facility # 456910



Photo # 385 From inspection 708902565 conducted on 12/19/2023 PRV vent line lacks cap



Photo # 1910 PRV vent line lacks cap