

Final Reclamation and Stormwater Inspection

Date: 12/29/23

Operator: Bonanza Creek Energy Operating
Company LLC - 8960

Location ID: 302895

Inspection Document #: 713900241

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pronghorn #31-21
Location ID: 302895




Photo 1. The photo was taken from the well location facing South. The photo illustrates the entrance to the access road.

Photo 2. The photo was taken from the well location facing South. The photo illustrates the subsidence along the access road.

Inspection Photos
Location Name: Pronghorn #31-21
Location ID: 302895




Photo 3. The photo was taken from the well location facing Southeast. The photo illustrates the cutslope has not been graded or recontoured.

Photo 4. The photo was taken from the well location facing Southwest. The photo illustrates the bare patch of soil from where the well itself was located.

Inspection Photos
Location Name: Pronghorn #31-21
Location ID: 302895




Photo 5. The photo was taken from the well location facing Northwest. The photo illustrates the well location from the top of the cutslope.

Photo 6. The photo was taken from the well location facing North. Refer to the comment for photo 5.