

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-05 Pad

Location ID: 334427

Date: 1/3/2024



Location Entrance – Photo #08483



Wellheads – Photo #08486

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-05 Pad

Location ID: 334427

Date: 1/3/2024



Separators – Photo #08485



Tank Battery – Photo #08488



Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-05 Pad

Location ID: 334427

Date: 1/3/2024



Lack of Stabilization – Photo #08484



Lack of Stabilization – Photo #08490

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-05 Pad

Location ID: 334427

Date: 1/3/2024



Lack of Stabilization – Photo #08491



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08492**