

Inspection Photos

Loc: 309118

Operator: OGRIS OPERATING LLC

Inspection Date: 1/3/2024

County: Las Animas



Inspection Photos



Photo 1. There are two spots of oil stained gravel neat to the wellhead.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 309118 | Date: 1/3/2024

Inspection Photos



Photo 2. There is oil in the engine skid that needs to be cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 309118 | Date: 1/3/2024

Inspection Photos



Photo 3. Facing east at the location and fill slope.

