

Inspection Photos

Loc: 308799

Operator: OGRIS OPERATING LLC

Inspection Date: 1/3/2024

County: Las Animas



Inspection Photos



Photo 1. This area of the road side near the wellsite has eroded and needs to be repaired. .



Inspection Photos



Photo 2. Facing southwest toward the wellsite location.



Inspection Photos



Photo 3. There is a dripping leak at the wellhead.



Inspection Photos



Photo 4. There is oil in the engine skid that needs to be cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 308799 | Date: 1/3/2024

Inspection Photos



Photo 5. Facing northeast at the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 308799 | Date: 1/3/2024