

# Interim and Stormwater Inspection

December 8, 2023

Operator: Verdad Oil & Gas Co- #10651

Location ID: 452118

Inspection Document #: 709400715

Weld County, CO

SWSE Section 17 T1N R64W

Reed Wold  
Reclamation Specialist, COGCC




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Warner 17-14 Tank Battery  
Facility ID: 452118



**Photo 1.** Photo taken of location sign.



**Photo 2.** Photo taken of tank battery. Photo taken facing southwest.

**Inspection Photos**  
**Location Name: Warner 17-14 Tank Battery**  
**Facility ID: 452118**

Dec 8, 2023 at 10:43:58 AM  
Keenesburg CO 80643  
United States



**Photo 3.** Photo taken of perimeter ditch on east side of pad.  
Photo taken facing south.

Dec 8, 2023 at 10:44:02 AM  
Keenesburg CO 80643  
United States



**Photo 4.** Photo taken of perimeter ditch Photo taken facing  
North.

**Inspection Photos**

**Location Name: Warner 17-14 Tank Battery**

**Facility ID: 452118**

Dec 8, 2023 at 10:44:24 AM  
Keenesburg CO 80643  
United States



**Photo 5.** Photo taken of perimeter ditch. Photo taken facing west

Dec 8, 2023 at 10:44:27 AM  
Keenesburg CO 80643  
United States



**Photo 6.** Photo of undisturbed vegetated area for reference next to pad. Photo tank facing east.

Inspection Photos

Location Name: Warner 17-14 Tank Battery

Facility ID: 452118

Dec 8, 2023 at 10:44:56 AM  
Keenesburg CO 80643  
United States



Dec 8, 2023 at 10:45:18 AM  
Keenesburg CO 80643  
United States



**Photo 7.** Photo of cut slope area on site, no soil stabilization present. Photo tank facing west.

**Photo 8.** Photo of bare topsoil stockpile. Photo tank facing west.



Inspection Photos  
Location Name: Warner 17-14 Tank Battery  
Facility ID: 452118

Dec 8, 2023 at 10:46:22 AM  
Keenesburg CO 80643  
United States



**Photo 9.** Photo of bare soil on south side of location. Photo tank facing east.

Dec 8, 2023 at 10:46:50 AM  
Keenesburg CO 80643  
United States



**Photo 10.** Photo of bare topsoil stockpile on south side of pad. Photo tank facing southeast.

Inspection Photos  
Location Name: Warner 17-14 Tank Battery  
Facility ID: 452118

Dec 8, 2023 at 10:49:27 AM  
Keenesburg CO 80643  
United States



**Photo 11.** Photo taken of perimeter ditch on north side of pad. Photo taken facing east.

Dec 8, 2023 at 10:48:48 AM  
Keenesburg CO 80643  
United States



**Photo 12.** Photo taken of perimeter ditch along access road on west side of pad. Photo taken facing south.