

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/05/2024

Submitted Date:

01/06/2024

Document Number:

707602215**FIELD INSPECTION FORM**Loc ID 483510 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484001	WELL	AP	03/13/2023		123-52071	Bishop A18-742	DG

**General Comment:**[This is a DRILLING inspection.](#)[Well\(s\): 1: Drilling | DG.](#)[New well GPS coordinates: 40.505384 / -104.585581](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	DRILLING/RECOMP			
Comment:	Access / Entrance; site safety signage posted.			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: _____
<b>Good Housekeeping:</b>				
Type	STORAGE OF SUPL			
Comment:	Adequate			
Corrective Action:			Date:	
Type	OTHER			
Comment:	Sound monitors installed outside at 4 corners of sound walls. Enhanced sound barriers installed. Low profile lighting installed for after dusk operations.			
Corrective Action:			Date:	
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No _____				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	LOCATION			
Comment:	Sound walls on 4 sides of location.			
Corrective Action:			Date:	
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities									
Facility ID:	484001	Type:	WELL	API Number:	123-52071	Status:	AP	Insp. Status:	DG
Well Drilling									
Rig:	Rig Name: Patterson UTI 268		Pusher/Rig Manager: John Drahota						
	Permit Posted: SATISFACTORY		Access Sign: SATISFACTORY						
Well Control Equipment:									
	Pipe Ram: YES	Blind Ram: YES	Hydril Type: YES						
	Pressure Test BOP: Pass	Test Pressure PSI: 5000	Safety Plan: YES						
Drill Fluids Management:									
	Lined Pit:	Unlined Pit:	Closed Loop: YES	Semi-Closed Loop:					
	Multi-Well: YES	Disposal Location: Waste Management LLC							
Comment:	At the time of inspection: Drilling: 17,759' TD. Running casing: 9,383'. Well is #1 of 16 to be drilled. Sound monitors installed outside at 4 corners of sound walls. Enhanced sound barriers installed. Low profile lighting installed for after dusk operations. Site safety plan posted.								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Waddles	Pass					
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<b>CECMC Inspection Report Summary:</b>  On FRI 01/05/2024 at approximately 11:58 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: A07-01/Pad Location ID: 483510 Well Name(s): Bishop A18-742. API: 123-52071. Location County: Weld County, Colorado Weather: Partly Sunny, dry.  While there, I observed: Well(s): 1: Drilling   DG. New well GPS coordinates: 40.505384 / -104.585581  During this inspection, NO possible compliance issues were observed.  This is a summary of the inspection report.	evinsb	01/06/2024

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602217	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6383964">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6383964</a>