

Inspection Photos
Location Name: Craig #2
Location ID: 327437




Photo 1 – Wellhead – Stained Soil



Photo 2 – Wellhead – Stained Soil

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 3 – Wellhead – Stained Soil



Photo 4 – Wellhead – Stained Soil

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 5 – Pumping Unit



Photo 6 – Wellhead Sign

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 7 – Stained Soil at Skim Tank