

# Inspection Photos

Loc: 309509

Operator: OGRIS OPERATING LLC

Inspection Date: 1/3/2024

County: Las Animas



Inspection Photos



**Photo 1.** Facing east toward the wellsite.



Inspection Photos



**Photo 2.** Well sign is posted at the meter shed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 309509 | Date: 1/3/2024

Inspection Photos



**Photo 3.** Facing east toward the well.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 309509 | Date: 1/3/2024

Inspection Photos



**Photo 4.** Facing toward the fill slope which is stabilized with vegetation cover.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 309509 | Date: 1/3/2024