

Inspection Photos

Loc: 308802

Operator: OGRIS OPERATING LLC

Inspection Date: 1/3/2024

County: Las Animas



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 308802 | Date: 1/3/2024

Inspection Photos



Photo 2. Facing northwest toward the interim reclamation area.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 308802 | Date: 1/3/2024

Inspection Photos



Photo 3. Well sign posted at meter shed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 308802 | Date: 1/3/2024