

# Inspection Photos

Loc: 309510

Operator: OGRIS OPERATING LLC

Inspection Date: 1/3/2024

County: Las Animas



**COLORADO**  
**Energy & Carbon Management**  
**Commission**  
Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east along the access road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc: 309510 | Date: 1/3/2024



## Inspection Photos



**Photo 2.** Facing east toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc: 309510 | Date: 1/3/2024



## Inspection Photos



**Photo 3.** The engine skid has oil and has spilled out onto the ground.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Loc: 309510 | Date: 1/3/2024



## Inspection Photos



**Photo 3.** Facing toward the wellhead.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 309510 | Date: 1/3/2024