

# Final Reclamation Inspection

December 28th, 2023

Operator: Simcoe LLC - 10749

Location ID: 325798

Inspection Document #: 714000277

La Plata County, CO

Township: SENW 9 34N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Sally Jo Lorett A1  
Location ID: 325798



Photo 1. View of the well disturbance from the entrance facing center.





# Inspection Photos

Location Name: Sally Jo Loret A1

Location ID: 325798



**Photo 2.** View of rill erosion forming in the northern area of the disturbance.

API #: 067-07002



Inspection Photos  
Location Name: Sally Jo Loret A1  
Location ID: 325798

12/28/23  
+37.208762,-107.725997  
229° SW



**Photo 3.** View of the southern interim reclamation facing southwest.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-07002



Inspection Photos

Location Name: Sally Jo Lorett A1

Location ID: 325798



**Photo 4.** Reference area comprised of poa secunda sagebrush, indian rice grass and juniper.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-07002