

Final Reclamation Inspection

December 28th, 2023

Operator: Simcoe LLC - 10749

Location ID: 326586

Inspection Document #: 714000285

La Plata County, CO

Township: SWSW 8 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lemon G 2
Location ID: 326586



Photo 1. View of the well disturbance from the entrance facing center.

Inspection Photos
Location Name: Lemon G 2
Location ID: 326586



12/28/23
+37.201635,-107.746127
271° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the southern interim reclamation area.

API #: 067-08352

Inspection Photos
Location Name: Lemon G 2
Location ID: 326586



Photo 3. View of trash/debris on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08352

Inspection Photos
Location Name: Lemon G 2
Location ID: 326586



12/28/23
+37.201630,-107.745610
110° E

Photo 4. View of weedy mullein debris observed in center of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08352

Inspection Photos
Location Name: Lemon G 2
Location ID: 326586



Photo 5. Severe gully erosion forming in the southern interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08352

Inspection Photos
Location Name: Lemon G 2
Location ID: 326586



Photo 6. View of reference area comprised of smooth brome, sagebrush and rabbit brush.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08352