

Inspection Photos  
Location Name: Almquist 1-35  
Location ID: 321277



Photo 1 WH Sign.




Photo 2 WH.



Inspection Photos  
Location Name: Almquist 1-35  
Location ID: 321277



Photo 3 Fugitive gas recovery device.



Photo 4 TB sign is peeling.

**Inspection Photos**  
**Location Name: Almquist 1-35**  
**Location ID: 321277**



**Photo 7 TB.**



**Photo 6 Horizontal Heated Separator & Gas Meter Run, card indicates current calibration.**