

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-3BB (PD30) Pad

Location #: 334752



Photo # 1982 From entrance to location



Photo # 1983 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-3BB (PD30) Pad

Location #: 334752



Photo # 1984 Location



Photo # 1985 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-3BB (PD30) Pad

Location #: 334752



Jan 8, 2024 at 11:50:44 AM
CO

Photo # 1986 Location



Jan 8, 2024 at 11:51:06 AM
CO

Photo # 1987 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-3BB (PD30) Pad

Location #: 334752



Photo # 1988 Location



Photo # 1989 Chemical tank label peeling & illegible



Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-3BB (PD30) Pad

Location #: 334752



Photo # 1990 Hole in liner/liner needs maintenance



Photo # 1991 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-3BB (PD30) Pad

Location #: 334752



Photo # 1992 Holes in liner/liner needs maintenance



Photo # 1993 Holes in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 30-3BB (PD30) Pad

Location #: 334752



Photo # 1994 Debris



Photo # 1995 Debris