

Final Reclamation Inspection

January 3rd, 2024

Operator: Enduring Resources LLC - 10679

Location ID: 307020

Inspection Document #: 714000299

La Plata County, CO

Township: NENW 23 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McCarville 2
Location ID: 307020



Photo 1. View of the disturbance taken from the entrance facing center.



Inspection Photos
Location Name: McCarville 2
Location ID: 307020



Photo 2. Cardinal photos taken from the center of the proposed well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: McCarville 2
Location ID: 307020



Photo 3. Cardinal photos taken from the center of the proposed well pad. Left photo facing south, right photo facing west. Note: stake observed in previous inspection has been removed. No evidence the disturbance was ever constructed



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09574