

Final Reclamation Inspection

January 3rd, 2024

Operator: Enduring Resources LLC - 10663

Location ID: 333788

Inspection Document #: 714000300

La Plata County, CO

Township: NWSE 24 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ute C 3
Location ID: 333788

1/3/24
+37.087184,-107.882735
201° S



Photo 1. View of the disturbance taken from the entrance facing center.



Inspection Photos
Location Name: Ute C 3
Location ID: 333788

1/3/24
+37.086729,-107.882841
67° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the eastern interim reclamation area facing northeast.

API #: 067-07644

Inspection Photos
Location Name: Ute C 3
Location ID: 333788



Photo 3. View of weedy debris observed on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07644